



FIRE ESCAPE ENGINEERS

A MEMBER OF THE FIRE ESCAPE SERVICES NETWORK

PRE-LOAD TEST EVALUATION RESULTS

FAILED MINOR

Pre Existing Non Conforming



PERFORMED AT: **E**
side
31 Newbury St (Roof) Boston MA

AUTHORITY HAVING JURISDICTION:
NEIL SULLIVAN

INSPECTION DATE **January 29 2025**
REPORT DATE **March 10 2025**
REPORT EXPIRES **April 10 2025**

PREPARED BY:
FIRE ESCAPE ENGINEERS

NOT to be used as a Construction Control Document unless noted and Formal Repair Report attached.

This document expires 30 days from date of delivery to owner/agent via email or mail unless Design Professional or Other are retained for Engineer Oversight in writing.



PRE-LOAD TEST INITIAL EVALUATION PASS/FAIL REPORT

E 31 Newbury St (Roof) Boston MA
side

Jan 29 2025
Site Inspection Date

pg 2



Overall Structural	Overall Paint	Supports/ Cement	Grating/ Platforms	Rails	Stringers	Treads	Cantilever/ Balanced I	Fixed Ladder	Cement Pads & Footings	Catwalk
<input type="checkbox"/> Life Safety (LS)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Imminent Safety Hazard (ISH)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/> Missing	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/> PreExisting NonConforming (PENC)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/> Poor/Fail	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> PASS other evidence of strength	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Not Applicable (N/A)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
25%	Percent Fail	0-25%	100%					25%	N/A	100%

2022 IFC 1104.16.5.1 Fire escape stairs must be examined every 5 years by a design professional or others acceptable to the Authority Having Jurisdiction and inspection report must be submitted to the AHJ.

IBC 1001.3.3 All fire escapes shall be examined and/or tested and certified every five years by a design professional or others acceptable who will then submit an affidavit city official.

ICC 2015 104.7.2 Technical assistance. To determine the acceptability of technologies, processes, products, facilities, materials and uses attending the design, operation or use of a building or premises subject to inspection by the fire code official, the fire code official is authorized to require the owner or agent to provide, without charge to the jurisdiction, a technical opinion and report. The opinion and report shall be prepared by a qualified engineer, specialist, laboratory or fire safety specialty organization acceptable to the fire code official and shall analyze the fire safety properties of the design, operation or use of the building or premises and the facilities and appurtenances situated thereon, to recommend necessary changes. The fire code official is authorized to require design submittals to be prepared by, and bear the stamp of, a registered design professional

PRE-LOAD TEST INITIAL EVALUATION PASS/FAIL REPORT

E 31 Newbury St (Roof) Boston MA
side

Jan 29 2025
Site Inspection Date






PRE-LOAD TEST INITIAL EVALUATION PASS/FAIL REPORT

E 31 Newbury St (Roof) Boston MA
side

Jan 29 2025
Site Inspection Date



PRE-LOAD TEST INITIAL EVALUATION PASS/FAIL REPORT



E
side

31 Newbury St (Roof) Boston MA

Jan 29 2025
Site Inspection Date

Paint Requirements - Surface rust, sealant, and greasing:

1) The fire escape system is made of:

- IRON/STEEL
 METAL (OTHER)
 WOOD
 MASONRY
 GLASS
 MIXED
 H. DEPOT LADDER
 PAINTED
 STAINED
 MEMB
 ALUMINUM
 STEEL & WOOD
 WOOD/COMPOSITE
 CONCRETE
 BRICK
 TILED
 NO FE ON THE BLDG
 GALVANIZED
 PRIMED
 PRESSURE TREATED
 OTHER

2) This Fire Escape System is maintained/painted/stained and/or weatherproofed.

Pass

Overall Paint PASS. Recommend to power wash and seal all major joints to prevent water intrusion into structural connections.

3) The owner is notified, by email or hand delivered, that EPA Lead Paint Rules apply because the FE system was built before 1978.

Pass

Pass: Overall Paint Pass: EPA rules apply for Lead Paint 1978. Renovator's license not required. Welding not approved as repair method.

Structural Requirements - internal rust, rebolting, reinforcement and replacement:

4) All welds PASS by visual observation only, unless noted: re-bolted, x ray or load tested are structurally sound having **NO** internal rust jacking, external surface rust and/or material deterioration.

Pass RLT

Overall the Structural Welds PASS. Pending load test or other evidence of strength otherwise liability disclaimer letter signed by owner.

5) Overall - fire escape system

Fail Minor

is structurally sound having **NO** internal rust jacking, external surface rust and/or material deterioration.

Overall Minor Structural FAIL. Wall that secures ladder needs repair.

6) Footings/Piers

N/A

are structurally sound having **NO** internal rust jacking, external surface rust and/or material deterioration - NO heaving or sinking

Not Applicable

7) Walls of attached fire escape system - by visual observation only on date of evaluation appear to be structurally sound having **NO** material deterioration - NO structural cracks/deterioration, deflection or bulging

Fail Minor

Overall Minor Structural Walls FAIL: Repairs required by mason or others qualified.

8) Supports into masonry wall

Pass RLT

are structurally sound having **NO** material deterioration - NO structural cracks/deterioration, rust jacking, deflection or spalling

Overall Structural Supports (bracket, thru-bolt, legs) PASS. Pending load test or other evidence of strength otherwise liability disclaimer letter signed by

9) Thru bolts into wood structure or masonry walls

N/A

are structurally sound having **NO** material deterioration - NO structural cracks/deterioration, rust jacking, deflection or wood rot

Not Applicable

10) Platforms, Slats, Grating, Mesh, Cement, Cast Iron, Wood and Angle and or Steel

Missing

Frame are structurally sound having **NO** material deterioration - **NO** internal rust jacking or external surface rust or wood rot

Overall Major Structural Platforms, Slats, Grating FAIL. Missing Component(s).

11) Stair Stringers, Upper & Lower Hanger Clips

N/A

are structurally sound having **NO** material deterioration - **NO** internal rust jacking or external surface rust or wood rot

Not Applicable

12) Stair Treads: Plate, Slats, Grating & Bolts and/or Welds

N/A

are structurally sound having **NO** material deterioration - **NO** internal rust jacking or external surface rust or wood rot

Not Applicable

13) Railings - on platforms, stairs & catwalks

N/A

are structurally sound having **NO** material deterioration - **NO** internal rust jacking or external surface rust or wood rot

Not Applicable

14) Fixed Ladders to Roof and/or to Grade & Bolts and/or Welds

Fail Minor

are structurally sound having **NO** material deterioration - **NO** internal rust jacking or external surface rust or wood rot or spalling

Overall Minor Structural FAIL. Wall that secures ladder needs repair.

15) Balanced Ladders: Bolts and/or Welds, Weight, Release Mechanism and other components

N/A

are structurally sound having **NO** material deterioration - **NO** internal rust jacking or external surface rust and are to grade/public way

Not Applicable

16) Cantilevers: Bolts and/or Welds, Weight Box, Release Mechanism and other components

N/A

are structurally sound having **NO** material deterioration - **NO** internal rust jacking or external surface rust and are to grade/public way

Not Applicable

17) Catwalks & Bolts and/or Welds are structurally sound having **NO** material deterioration - **NO** internal rust jacking or external surface rust and lead to the fire escape and completes to grade

Missing

Catwalk is missing.

PRE-LOAD TEST INITIAL EVALUATION PASS/FAIL REPORT

Jan 29 2025
Site Inspection DateE
side 31 Newbury St (Roof) Boston MA

Code Requirements - Fabrication, Installation, Modification, and Code Upgrades

18) All fabrication, installation and maintenance of fire escape is to code and met industry standards on date of installation.

Code

Design and Fabrication did NOT meet code standards on date of installation.

19) There are **NO** pre-existing non-conforming issues requiring AHJ notification for approval.

Code

AHJ approval required.

20) All components: doors, windows, window guards, cages and gates are single action requiring no special knowledge, no keys and no obstruction and lead to public way

Code

Design and Fabrication did NOT meet code standards on date of installation.

21) All electrical power is 10 feet or more away from fire escape or covered to code.

Pass

Design and Fabrication met code standards on date of installation.

22) Overall the fire escape is not illuminated due to pre-existing code on date of install.

Code

Overall Code Issues: NO illumination visible. Local Ordinance may apply to upgrade egress lighting.

23) Overall fire escape system has no interior or exterior obstructions such as a/c units, plants, bikes, trash etc.

Code

Overall Code Issues: Obstruction, Debris/Trash/Plant Pots/Barriers, need to be removed.

24) Overall fire escape system has no storage of flammables or code restricted items on, in or

Pass

Overall Code Issues: NO Flammables on or under system i.e. BBQ or anything powered by gasoline.

25) Do all egress systems allow for clear and legal access to public fairway or dispersal area?

Pass

Overall Code Issues: NOT Blocked and has access to public way.

ALL FIRE ESCAPES MUST BE STRUCTURALLY SOUND AND KEPT PAINTED AS PER CODE. Structural connections must be free of all internal rust and sealed from water intrusion. Spot paint every 3-5 years, full paint every 7-10 years and maintain sealant on all critical structural connections.

IFC 1104.16.5.1 Fire escape stairs must be examined every 5 years by a design professional or others acceptable to the Authority Having Jurisdiction and inspection report must be submitted to the AHJ. IBC 1001.3.3 All fire escapes shall be examined and/or tested and certified every five years by a design professional or others acceptable who will then submit an affidavit city official. NFPA LIFE SAFETY CODE 101 7.2.8.6.2 The Authority Having Jurisdiction (AHJ) shall approve any fire escape by Load Test or Certification (other evidence of strength). ICC 104.7.2 Technical assistance. The fire code official is authorized to require the owner or agent to provide, without charge to the jurisdiction, a technical opinion and report. The opinion and report shall be prepared by a specialist or a fire safety specialty organization acceptable to the fire code official to analyze the fire escape and appurtenances situated thereon, to recommend necessary changes. The fire code official is authorized to require design submittals to be prepared by, and bear the stamp of, a registered design professional. OSHA 1910.37 Exit routes must be maintained during construction, repairs, alterations or provide alternative egress with equivalent level of safety. (permit issued if egress is certified or with egress scaffolding) All insurance companies: All final certifications to AHJ (load tested or other evidence of strength) must be submitted for acceptance by insurance company to avoid coverage issues.



PRE-LOAD TEST INITIAL EVALUATION PASS/FAIL REPORT

E 31 Newbury St (Roof) Boston MA

Jan 29 2025
Site Inspection Date

pg 7



1. Overall Structural:

Issues Exist

25%



2. Overall Paint:

Fair

0-25%



3. Code:

Issues Exist

75-100%

This pre load test evaluation was requested at this location to confirm that the fire escape system is structurally sound and has been kept painted as is required by code. Certification can be done by load test, other evidence of strength or an opinion affidavit with a disclaimer of liability waiver form.

This is a five story brick building with a fire escape system made of steel and aluminum and consisting of ladders to a neighboring roof that acts as a dispersal area. This system did not pass due to the following minor issues:

Fixed Ladder

- The wall supporting the exterior fixed ladder requires repairs to ensure structural stability and safe egress.
- The interior ladder has sharp edges due to angled cuts at the top, posing a safety hazard. The edges should be smoothed or properly finished to prevent injury.
- The top few rungs of the interior ladder are not securely connected to the wall, reducing stability and increasing the risk of failure under load. A platform break should be installed at the top of the well as well as an additional ladder to transition from the platform to roof after the hatch deploys, if not, additional supports or wall anchors should be installed to reinforce the ladder and ensure safe use.

Catwalk - There is no catwalk connecting the roof hatch to the exterior ladder, creating a hazardous gap in the egress path. This absence forces individuals to traverse the roof surface, which may be unsafe, especially in weather and emergency situations. A properly designed and code-compliant catwalk should be installed to ensure a safe and direct transition between the hatch and the exterior ladder.

Other

- The ladder providing access to the roof is located inside a bathroom closet, which is an unconventional and potentially non-compliant placement that may obstruct emergency egress. Relocation or an alternative means of access should be evaluated for compliance with safety regulations.
- The roof hatch is difficult to operate, potentially delaying evacuation in an emergency. Proper maintenance or replacement with a code-compliant, single-action, easily operable hatch is recommended.
- There is no platform at the top of the access well, requiring individuals to stand on the ladder while opening the hatch. This creates a significant safety hazard. Installing a compliant landing platform is recommended to enhance safety and accessibility.
- The roof hatch lacks a transfer step, making it difficult and unsafe to climb onto the roof from the ladder. A properly designed and code-compliant transfer step should be installed to facilitate safe egress.
- The angle at which the hatch door rests creates a head obstruction when exiting.
- No visible emergency egress lighting is present, which may compromise visibility during an evacuation.

SEE VIDEO-PHOTO EVALUATION FOR MORE DETAILED INFORMATION * THIS IS NOT A CONSTRUCTION CONTROL DOCUMENT

Overall the paint PASS: Spot paint on system required after repairs. Recommend to power wash and seal all major joints to prevent water intrusion into structural connections. Fire Escapes, must be maintained/ painted every 5-7 years as per manufactures recommendation.

Our inspector found code issues related to AHJ (Authority Having Jurisdiction) or PENC (pre-existing non-conforming) requirements for this Fire Escape system. (issues detailed above)



PRE-LOAD TEST INITIAL EVALUATION PASS/FAIL REPORT



E 31 Newbury St (Roof) Boston MA
side

Jan 29 2025
Site Inspection Date


STRUCTURAL SUPPORT COMPONENTS




INITIAL EVALUATION
PASS/FAIL REPORT
TYPICAL HISTORICAL
EXISTING CONDITIONS




1 S1-BALC-WITH-BRACKET
SCALE: 3/8" = 1'-0"



7 S1-3D-EVAL-RENDERING-BALCONY-NO-BRACKET
SCALE: 1/2" = 1'-0"



3 S2-BALC-WITH-BRACKET
SCALE: 3/8" = 1'-0"



4 S2-3D-EVAL-RENDERING-BALC-BRACKET
SCALE: 1/2" = 1'-0"

COPYRIGHT 2023 ALL RIGHTS RESERVED

12/17/2023 11:57:27 AM

STRUCTURAL SUPPORT COMPONENTS

S1&2

FIRE ESCAPE ENGINEERS | 616 Washington Street, St #3 Lynn, MA 01901 | www.fireescapeengineers.com | 800-649-3333




PRE-LOAD TEST INITIAL EVALUATION PASS/FAIL REPORT

E 31 Newbury St (Roof) Boston MA
side

Jan 29 2025
Site Inspection Date




INITIAL EVALUATION
PASS/FAIL REPORT
TYPICAL HISTORICAL
EXISTING CONDITIONS



1 S3-BALC-WITH-POST-TO-GROUND
SCALE: 3/8" = 1'-0"

2 S3-3D-RENDERING-BALCONY POST TO GROUND
SCALE: 12" = 1'-0"



3 S4-BALC-WITH-THRU BOLT & PLATE
SCALE: 3/8" = 1'-0"

4 S4-3D-EVAL-RENDERING-BALC-WITH THRU BOLT
SCALE: 12" = 1'-0"

COPYRIGHT 2023 ALL RIGHTS RESERVED

12/17/2023 11:57:28 AM

STRUCTURAL SUPPORT COMPONENTS

S3&4

FIRE ESCAPE ENGINEERS | 616 Washington Street, 5th Fl Lynn, MA 01901 | www.fireescapeengineers.com | 800-649-3333

PRE-LOAD TEST INITIAL EVALUATION PASS/FAIL REPORT


E 31 Newbury St (Roof) Boston MA
side

Jan 29 2025
Site Inspection Date

PLATFORM and STAIRS COMPONENTS



INITIAL EVALUATION
PASS/FAIL REPORT
TYPICAL HISTORICAL
EXISTING CONDITIONS



1 E1-STAIR TYPICAL
SCALE: 1/4" = 1'-0"



2 E1-TOP
SCALE: 3/4" = 1'-0"



3 E1- BOTTOM
SCALE: 3/4" = 1'-0"




4 E1- 3D-EVAL-RENDERING-STAIR TYPICAL
SCALE: 1/2" = 1'-0"




5 T1- TREAD
SCALE: 1" = 1'-0"

CHECKER PLATE TREAD MAKE
24"x24" GRATING COMPONENT.
GISD WILL TELL WHETHER ITS A
CONCRETE GRATE OF
CHECKER PLATE




7 T2 CHECKER PLATE TREAD - PLAN
SCALE: 1" = 1'-0"



6 T1 HISTORIC TREAD - PLAN
SCALE: 1" = 1'-0"

BAR GRATE WITH
SPACES AND A THRU
BOLT



10 G1-3D-EVAL-TREAD
SCALE: 1/2" = 1'-0"

COPYRIGHT 2023 ALL RIGHTS RESERVED

12/17/2023 11:57:26 AM

TREAD & GRATING COMPONENTS

E1,G1&T1



PRE-LOAD TEST INITIAL EVALUATION PASS/FAIL REPORT


E 31 Newbury St (Roof) Boston MA
side

Jan 29 2025
Site Inspection Date

CEMENT SLAB, FOOTING & PAD COMPONENTS




INITIAL EVALUATION
PASS/FAIL REPORT
TYPICAL HISTORICAL
EXISTING CONDITIONS



1 C2-CEMENT SLAB, FOOTING AND PAD
SCALE: 3/8" = 1'-0"

2 C2-3D-EVAL-CONCRETE FOOTING
SCALE: 12" = 1'-0"



3 L1-BALCONY AND LADDER
SCALE: 3/8" = 1'-0"

4 L1-3D-EVAL-BALCONY & LADDER
SCALE: 12" = 1'-0"

COPYRIGHT 2023 ALL RIGHTS RESERVED

PRE-LOAD TEST INITIAL EVALUATION PASS/FAIL REPORT



E 31 Newbury St (Roof) Boston MA
side

Jan 29 2025
Site Inspection Date

CANTILEVER STAIRS



INITIAL EVALUATION
PASS/FAIL REPORT
TYPICAL HISTORICAL
EXISTING CONDITIONS



1 C1-STAIR CANTILEVER

SCALE: 1/4" = 1'-0"

6 C1-ENLGD. 3D BEARING ROD

SCALE:



LOWER CANTILEVER
STAIR RELEASE ROD
AND PUSH BAR

2 C1-TOP

SCALE: 1/2" = 1'-0"




3 C1-BEARING ROD

SCALE: 1/2" = 1'-0"



4 C1-BRACKET BOTTOM

SCALE: 1/2" = 1'-0"



7 C1-3D-EVAL-RENDERING-STAIR CANTILEVER

SCALE: 1/2" = 1'-0"

COPYRIGHT 2023 ALL RIGHTS RESERVED

12/17/2023 11:57:22 AM

CANTILEVER STAIRS

C1

FIRE ESCAPE ENGINEERS | 616 Washington Street, St #3 Lynn, MA 01901 | www.fireescapeengineers.com | 800-649-3333



PRE-LOAD TEST INITIAL EVALUATION PASS/FAIL REPORT


E 31 Newbury St (Roof) Boston MA
side

Jan 29 2025
Site Inspection Date

CATWALK COMPONENTS




INITIAL EVALUATION
PASS/FAIL REPORT
TYPICAL HISTORICAL
EXISTING CONDITIONS



1 C3-CATWALK AND COMPONENTS
SCALE: 3/8" = 1'-0"



2 C3-3D-EVAL-RENDERING-CATWALK
SCALE: 12" = 1'-0"



4 E2-RAIL WITH EMBED
SCALE: 3/8" = 1'-0"



6 E2-3D-RENDERING-RAILING
SCALE: 12" = 1'-0"

COPYRIGHT 2023 ALL RIGHTS RESERVED

13

12/17/2023 11:57:24 AM

CATWALK COMPONENTS

C3&E2

FIRE ESCAPE ENGINEERS | 616 Washington Street, St #3 Lynn, MA 01901 | www.fireescapeengineers.com | 800-649-3333

NOT to be used as a Construction Control Document unless noted and Formal Repair Report attached.

This document expires 30 days from date of delivery to owner/agent via email or mail unless Design Professional or Other are retained for Engineer Oversight in writing.

PRE-LOAD TEST INITIAL EVALUATION PASS/FAIL REPORT



E 31 Newbury St (Roof) Boston MA

side

Jan 29 2025
Site Inspection Date

31 Newbury St (Roof)
Site Address
Sal Monteneri
Owner or Owner Agent
Boston MA 02116
City State Zip Code
(617) 728-2759
Phone fax
smonteneri@dlsaunders.com
email

FE Structural Format **DL Saunders**
Roof Ladders Owner or Owner Agent Company
Location E Mailing Address
FE Made Of Metal (other) Boston MA
City State Zip Code
Stories 4 Phone fax
of FEs on building 3 website

Boston MA 1010 Massachusetts Ave Boston MA 02118
Authority Having Jurisdiction Address City State Zip Code
neil.sullivan@boston.gov 617-961-3434
email Phone fax
Violation Number WRITTEN VIOLATION VERBAL N

Repair/Paint Vendor or Owner/Agent acceptable by AHJ to repair/paint fire escapes:
Repair Vendor or Agent: Company Name Repair Vendor or Agent: Contact Name License Number Repair Permit Number

This document is a. a Pass/Fail Report (not to be used as a construction control document)
OR b. a Fail Report with attached repairs report (with photos/drawings and repairs criteria as required for permit if permit is needed)

To the best of my Information, Knowledge, Belief and Opinion that the following statements are true and apply regarding this Fire Escape System as of the date of evaluation above.

- Indicate inspection was done by:
- a. a visual walk through of the Fire Escape System all accessible areas only. NO Load Test or destructive testing was performed. Safety hammer testing, scraping, poking, and chipping are all part of visual observation and resulting damage is owner's responsibility to repair or maintain.
 - b. an Evaluation of the Fire Escape System from the ground, with or without the use of visual aid, due to NO ACCESS or UNSAFE STRUCTURE WITH LIFE SAFETY ISSUES.

Fire Escape Passed? FAILED MINOR **Life Safety** Pre Existing Non Conforming

- The System is Certified by Load Test done by Engineering/Testing Agency at 100 lbs per sq foot.
- The System is Certified by Other Evidence of Strength (by full restoration or NEW) in lieu of load test.
- The System is Certified by Opinion Affidavit, accepted by AHJ as ready for use with opinion disclaimer of liability.
- Inspection/Evaluation determined the System FAILED. It is NOT structurally sound and/or painted.

ALL FIRE ESCAPES MUST BE STRUCTURALLY SOUND AND KEPT PAINTED AS PER CODE. Structural connections must be free of all internal rust and sealed from water intrusion. Spot paint every 3-5 years, full paint every 7-10 years and maintain sealant on all critical structural connections.


IFC 1104.16.5.1 Fire escape stairs must be examined every 5 years by a design professional or others acceptable to the Authority Having Jurisdiction and inspection report must be submitted to the AHJ. IBC 1001.3.3 All fire escapes shall be examined and/or tested and certified every five years by a design professional or others acceptable who will then submit an affidavit city official. NFPA LIFE SAFETY CODE 101 7.2.8.6.2 The Authority Having Jurisdiction (AHJ) shall approve any fire escape by Load Test or Certification (other evidence of strength).

Francisco Meneses Design Professional or Other Name CS-94862 License Number Jan/07/26 License Expires Date
866-649-0333 Phone 888-895-7507 fax Site Inspection Date
info@fireescapeengineers.com email 5898 Case ID

Fire Escape Engineers Design Company or Other Company Name
616 Washington St Address
Lynn MA 01901
City State Zip Code

X

peer reviewed by Fire Escape Engineer Francisco Meneses



PRE-LOAD TEST INITIAL EVALUATION PASS/FAIL REPORT**E**
side**31 Newbury St (Roof) Boston MA**Jan 29 2025
Site Inspection Date**Responsible Party Assignment as per Code****Fire Escape Inspectors Oversight Options:**

Further information for each option you may have interest in will be sent with a formal proposal upon request. Please reach out after reviewing these options with any questions or concerns. A signature is required with a 35% deposit to initiate any option.

Project Management Oversight (PMO): Oversee our network Vendor, or a Vendor of your choice, to do the work necessary to bring your fire escape into compliance and is certified by a final examination (a Load Test may still be required). Technical Repair report written for project. 3 to 5 Visits with a design professional. Zoom meeting to review all repairs and methodology with the chosen vendor is included. Pictures or video supplied by the vendor on a daily basis. unlimited phone calls or Facetime. Includes final certification. Can be a standalone service if you choose your own vendor.

Vendor Management Oversight: Oversee our Network Vendor, or a Vendor of your choice (who is a fully experienced fire escape technician), to do the work necessary to bring your fire escape into compliance and is certified by a final examination (a Load Test may still be required). Zoom meeting to review all repairs and methodology with the chosen vendor is included. Pictures or video supplied by the vendor on a daily basis. Unlimited phone calls or Facetime. Includes final certification. Can be a standalone service if you choose your own vendor.

Load Test: A stand-alone Load Test can be performed with a Deficiency Report (identifying outstanding distressed conditions not repaired or repaired poorly) if you choose your own vendor for the repair process. A Load Test is performed at 100 lb. per square foot and 200 lb. Lateral force on all railings. Weight used depends on square footage calculated A 5-year certification will be issued for one inspection cycle only.

Fire Escape Services: Restoration - Repairs - Repainting 4 Option Pricing

Full Restoration and Full Paint: Restoration will begin shortly after Emergency Repairs are completed if needed. All major structural connections will be cleaned, primed, sealed, and re-bolted. Any components with more than 25% material in any area will be reinforced or replaced. All Minor connections with internal rust will also be treated in the same manner. All Surface Rust is scraped, primed, sealed with a 50-year paintable silicone, and a full topcoat is applied following EPA Lead guidelines (DTM or Oil Base). After final examination by our Inspector (approved by AHJ) a certification with a 15-25-year structural warranty will be issued. This service will negate any future Load test requirement for up to 25 years with AHJ approval. Includes PMO

Spot Restoration and Full Paint All major connections with excessive internal rust will be cleaned, primed, sealed, and re-bolted. Any minor connections with excessive internal rust will be treated the same. Any components with more than 25% material in any area will be reinforced or replaced. There will be an Integrated Load Test and Dynamic Stress Test to components that were not restored. All Surface Rust is scraped, primed, sealed with a 50-year paintable silicone, and a full topcoat is applied following EPA Lead guidelines (DTM or Oil Base). After final examination by our Inspector (approved by AHJ) a certification with a 10-year structural warranty will be issued on only work performed. The cost of the Spot Restoration can be credited towards a Full Restoration within 5 years (price adjusted for inflation and labor rates at that time), some restrictions may apply. Includes Integrated Load Test and Dynamic Stress Test to components. Includes PMO.

Spot Repair and Spot Paint: Only distressed, extremely poor welding, and/or broken connections will be repaired as needed. Critical deteriorated material will be reinforced or replaced as needed. The entire system will be certified (for 5-years only) by a Full Load Test and Dynamic Stress Test. A Spot Paint includes scraping and priming: loose or peeling paint, surface rust, and repaired areas. A spot topcoat is applied following EPA Lead guidelines. No warranty is offered. Includes Load Test and Dynamic Stress Test to components. Includes VO.

PRE-LOAD TEST INITIAL EVALUATION PASS/FAIL REPORT

E 31 Newbury St (Roof) Boston MA
side

Jan 29 2025
Site Inspection Date

