




FIRE ESCAPE ENGINEERS

A MEMBER OF THE FIRE ESCAPE SERVICES NETWORK

PRE-LOAD TEST EVALUATION RESULTS

FAILED MAJOR

AHJ approval required



PERFORMED AT: **E**
side
39-45 Newbury St (Roof) Boston MA

AUTHORITY HAVING JURISDICTION:
NEIL SULLIVAN

INSPECTION DATE **January 14 2025**
REPORT DATE **March 10 2025**
REPORT EXPIRES **April 10 2025**

PREPARED BY:
FIRE ESCAPE ENGINEERS

NOT to be used as a Construction Control Document unless noted and Formal Repair Report attached.

This document expires 30 days from date of delivery to owner/agent via email or mail unless Design Professional or Other are retained for Engineer Oversight in writing.



PRE-LOAD TEST INITIAL EVALUATION PASS/FAIL REPORT

E 39-45 Newbury St (Roof) Boston MA
side

Jan 14 2025
Site Inspection Date

pg 2



Overall Structural	Overall Paint	Supports/ Cement	Grating/ Platforms	Rails	Stringers	Treads	Cantilever/ Balanced L	Fixed Ladder	Cement Pads & Footings	Catwalk	
<input type="checkbox"/> Life Safety (LS)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
<input type="checkbox"/> Imminent Safety Hazard (ISH)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
<input checked="" type="checkbox"/> Missing	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
<input type="checkbox"/> PreExisting NonConforming (PENC)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
<input checked="" type="checkbox"/> Poor/Fail	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
<input type="checkbox"/> PASS other evidence of strength	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
<input type="checkbox"/> Not Applicable (N/A)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
50%	Percent Fail	50%	25-50%	0-25%	25-50%	25%	25%	N/A	N/A	N/A	100%

2022 IFC 1104.16.5.1 Fire escape stairs must be examined every 5 years by a design professional or others acceptable to the Authority Having Jurisdiction and inspection report must be submitted to the AHJ.

IBC 1001.3.3 All fire escapes shall be examined and/or tested and certified every five years by a design professional or others acceptable who will then submit an affidavit city official.


ICC 2015 104.7.2 Technical assistance. To determine the acceptability of technologies, processes, products, facilities, materials and uses attending the design, operation or use of a building or premises subject to inspection by the fire code official, the fire code official is authorized to require the owner or agent to provide, without charge to the jurisdiction, a technical opinion and report. The opinion and report shall be prepared by a qualified engineer, specialist, laboratory or fire safety specialty organization acceptable to the fire code official and shall analyze the fire safety properties of the design, operation or use of the building or premises and the facilities and appurtenances situated thereon, to recommend necessary changes. The fire code official is authorized to require design submittals to be prepared by, and bear the stamp of, a registered design professional



PRE-LOAD TEST INITIAL EVALUATION PASS/FAIL REPORT

E 39-45 Newbury St (Roof) Boston MA
side


Jan 14 2025
Site Inspection Date



PRE-LOAD TEST INITIAL EVALUATION PASS/FAIL REPORT

E 39-45 Newbury St (Roof) Boston MA
side

Jan 14 2025
Site Inspection Date



PRE-LOAD TEST INITIAL EVALUATION PASS/FAIL REPORT

E **39-45 Newbury St (Roof) Boston MA**
side

Jan 14 2025
Site Inspection Date

Paint Requirements - Surface rust, sealant, and greasing:

1) The fire escape system is made of:

- IRON/STEEL METAL (OTHER) WOOD MASONRY GLASS MIXED H. DEPOT LADDER PAINTED STAINED MEMB
 ALUMINUM STEEL & WOOD WOOD/COMPOSITE CONCRETE BRICK TILED NO FE ON THE BLDG GALVANIZED PRIMED PRESSURE TREATED OTHER

2) This Fire Escape System is maintained/painted/stained and/or weatherproofed.

Fail Major

Overall Paint FAIL. Lack of routine maintenance requiring Full scrape, prime, seal, and paint.

3) The owner is notified, by email or hand delivered, that EPA Lead Paint Rules apply because the FE system was built before 1978.

Fail

Overall Paint FAIL: EPA rules apply for Lead Paint 1978. Renovator's license required. Welding not approved as repair method.

Structural Requirements - internal rust, rebolting, reinforcement and replacement:

4) All welds PASS by visual observation only, unless noted: re-bolted, x ray or load tested are structurally sound having NO internal rust jacking, external surface rust and/or material deterioration.

N/A

Not Applicable

5) Overall - fire escape system

Fail Major

is structurally sound having NO internal rust jacking, external surface rust and/or material deterioration.

Overall Major Structural FAIL. Internal rust causing Rust Jacking (RJ) of all suspect connections.

6) Footings/Piers

Fail Minor

are structurally sound having NO internal rust jacking, external surface rust and/or material deterioration - NO heaving or sinking

Overall Minor Structural Footing FAIL. Some connections require repairs and sealed with water sealant.

7) Walls of attached fire escape system - by visual observation only on date of evaluation appear to be structurally sound having NO material deterioration - NO structural cracks/deterioration, deflection or bulging

Pass RLT

Overall Structural Walls PASS.

8) Supports into masonry wall

Fail Major

are structurally sound having NO material deterioration - NO structural cracks/deterioration, rust jacking, deflection or spalling

Overall Major Structural Supports (bracket, thru-bolt, legs) FAIL: Loose and missing bolts need to be repaired.

9) Thru bolts into wood structure or masonry walls

N/A

are structurally sound having NO material deterioration - NO structural cracks/deterioration, rust jacking, deflection or wood rot

Not Applicable

10) Platforms, Slats, Grating, Mesh, Cement, Cast Iron, Wood and Angle and or Steel

Missing

Frame are structurally sound having NO material deterioration - NO internal rust jacking or external surface rust or wood rot

Overall Major Structural Platforms, Slats, Grating FAIL. Missing Component(s).

11) Stair Stringers, Upper & Lower Hanger Clips

Fail Major

are structurally sound having NO material deterioration - NO internal rust jacking or external surface rust or wood rot

Overall Major Stair Stringers FAIL. All bolted clips are suspect and require reinforcement (re-bolt) or replaced with new.

12) Stair Treads: Plate, Slats, Grating & Bolts and/or Welds

Fail Minor

are structurally sound having NO material deterioration - NO internal rust jacking or external surface rust or wood rot

Overall Minor Structural Treads FAIL. Internal rust causing Rust Jacking (RJ) of some suspect connections.

13) Railings - on platforms, stairs & catwalks

Fail Major

are structurally sound having NO material deterioration - NO internal rust jacking or external surface rust or wood rot

Overall Major Structural FAIL. Material loss and/or damaged component must be reinforced or replaced new

14) Fixed Ladders to Roof and/or to Grade & Bolts and/or Welds

N/A

are structurally sound having NO material deterioration - NO internal rust jacking or external surface rust or wood rot or spalling

Not Applicable

15) Balanced Ladders: Bolts and/or Welds, Weight, Release Mechanism and other components

N/A

are structurally sound having NO material deterioration - NO internal rust jacking or external surface rust and are to grade/public way

Not Applicable

16) Cantilevers: Bolts and/or Welds, Weight Box, Release Mechanism and other components

N/A

are structurally sound having NO material deterioration - NO internal rust jacking or external surface rust and are to grade/public way

Not Applicable

17) Catwalks & Bolts and/or Welds are structurally sound having NO material deterioration - NO internal rust jacking or external surface rust and lead to the fire escape and completes to grade

Missing

Catwalk is missing.

PRE-LOAD TEST INITIAL EVALUATION PASS/FAIL REPORT

Jan 14 2025
Site Inspection Date



E
side

39-45 Newbury St (Roof) Boston MA

Code Requirements - Fabrication, Installation, Modification, and Code Upgrades

18) All fabrication, installation and maintenance of fire escape is to code and met industry standards on date of installation.

Code

Design and Fabrication did not meet code standards on date of installation.

19) There are **NO** pre-existing non-conforming issues requiring AHJ notification for approval.

Pass

NO AHJ approval required.

20) All components: doors, windows, window guards, cages and gates are single action requiring no special knowledge, no keys and no obstruction and lead to public way

Pass

Design and Fabrication met code standards on date of installation.

21) All electrical power is 10 feet or more away from fire escape or covered to code.

Pass

Design and Fabrication met code standards on date of installation.

22) Overall the fire escape is not illuminated due to pre-existing code on date of install.

Code

Overall Code Issues: NO illumination visible. Local Ordinance may apply to upgrade egress lighting.

23) Overall fire escape system has no interior or exterior obstructions such as a/c units, plants, bikes, trash etc.

Pass

Overall Code Issues: NO Obstructions.

24) Overall fire escape system has no storage of flammables or code restricted items on, in or

Pass

Overall Code Issues: NO Flammables on or under system i.e. BBQ or anything powered by gasoline.

25) Do all egress systems allow for clear and legal access to public fairway or dispersal area?

Pass

Overall Code Issues: NOT Blocked and has access to public way.

ALL FIRE ESCAPES MUST BE STRUCTURALLY SOUND AND KEPT PAINTED AS PER CODE. Structural connections must be free of all internal rust and sealed from water intrusion. Spot paint every 3-5 years, full paint every 7-10 years and maintain sealant on all critical structural connections.

IFC 1104.16.5.1 Fire escape stairs must be examined every 5 years by a design professional or others acceptable to the Authority Having Jurisdiction and inspection report must be submitted to the AHJ. IBC 1001.3.3 All fire escapes shall be examined and/or tested and certified every five years by a design professional or others acceptable who will then submit an affidavit city official. NFPA LIFE SAFETY CODE 101 7.2.8.6.2 The Authority Having Jurisdiction (AHJ) shall approve any fire escape by Load Test or Certification (other evidence of strength). ICC 104.7.2 Technical assistance. The fire code official is authorized to require the owner or agent to provide, without charge to the jurisdiction, a technical opinion and report. The opinion and report shall be prepared by a specialist or a fire safety specialty organization acceptable to the fire code official to analyze the fire escape and appurtenances situated thereon, to recommend necessary changes. The fire code official is authorized to require design submittals to be prepared by, and bear the stamp of, a registered design professional. OSHA 1910.37 Exit routes must be maintained during construction, repairs, alterations or provide alternative egress with equivalent level of safety. (permit issued if egress is certified or with egress scaffolding) All insurance companies: All final certifications to AHJ (load tested or other evidence of strength) must be submitted for acceptance by insurance company to avoid coverage issues.

PRE-LOAD TEST INITIAL EVALUATION PASS/FAIL REPORT

E 39-45 Newbury St (Roof) Boston MA

Jan 14 2025
Site Inspection Date

pg 7



1. Overall Structural:

Poor/Fail

50%

This pre load test evaluation was requested at this location to confirm that the fire escape system is structurally sound and has been kept painted as is required by code. Certification can be done by load test, other evidence of strength or an opinion affidavit with a disclaimer of liability waiver form. This is a six story brick building with a fire escape system made of painted steel as well as wood and consisting of platforms with stairs and a stair well to grade. This system did not pass due to the following major issues:

SUPPORTS: On the steel stair, several bolts securing the platform are either loose or missing, compromising structural stability and safety.

PLATFORMS: The steel stair is missing a landing platform, making transitions unsafe and non-compliant with egress requirements. Installing a properly sized and secured platform is necessary to ensure safe movement and adherence to safety standards.

RAILS: The railing on the wooden stair closest to the alleyway is loose, compromising safety and stability. Reinforcement or reattachment is necessary to restore structural integrity.

STRINGERS: On the steel stair, the stringer bolts, which also serve as structural supports, are either loose or missing.

TREADS: Internal rust is beginning to cause rust jacking in the tread clips with the bolted hardware, leading to potential expansion and weakening of the connections. If left unaddressed, this could compromise the structural integrity of the bolts and stair system.

CATWALK: The egress path is incomplete due to the absence of a catwalk across the roof, which should connect both exits and lead to the stairwell.

OTHER: -The wooden systems are constructed partially using kiln-dried wood instead of pressure-treated wood, which reduces resistance to moisture, decay, and long-term durability in exterior conditions.

-The system may require an emergency lighting upgrade to ensure adequate illumination of the egress path during low-light conditions or power outages.

SEE VIDEO-PHOTO EVALUATION FOR MORE DETAILED INFORMATION *
THIS IS NOT A CONSTRUCTION CONTROL DOCUMENT



2. Overall Paint:

Poor/Fail

50%

Overall the paint FAIL: Full paint on system required after repairs. Recommend to power wash and seal all major joints to prevent water intrusion into structural connections.

Fire Escapes, must be maintained/ painted every 5-7 years as per manufactures recommendation.



3. Code:

Issues Exist

25-50%

Our inspector found code issues related to AHJ (Authority Having Jurisdiction) or PENC (pre-existing non-conforming) requirements for this Fire Escape system.

-Egress system may require code upgrade for emergency lighting.

-Missing platform and catwalks.

PRE-LOAD TEST INITIAL EVALUATION PASS/FAIL REPORT



E 39-45 Newbury St (Roof) Boston MA
side

Jan 14 2025
Site Inspection Date


STRUCTURAL SUPPORT COMPONENTS




INITIAL EVALUATION
PASS/FAIL REPORT
TYPICAL HISTORICAL
EXISTING CONDITIONS




1 S1-BALC-WITH-BRACKET
SCALE: 3/8" = 1'-0"



7 S1-3D-EVAL-RENDERING-BALCONY-NO-BRACKET
SCALE: 1/2" = 1'-0"



3 S2-BALC-WITH-BRACKET
SCALE: 3/8" = 1'-0"



4 S2-3D-EVAL-RENDERING-BALC-BRACKET
SCALE: 1/2" = 1'-0"

COPYRIGHT 2023 ALL RIGHTS RESERVED

12/17/2023 11:57:27 AM

STRUCTURAL SUPPORT COMPONENTS

S1&2

FIRE ESCAPE ENGINEERS | 616 Washington Street, St #3 Lynn, MA 01901 | www.fireescapeengineers.com | 800-649-3333




PRE-LOAD TEST INITIAL EVALUATION PASS/FAIL REPORT

E 39-45 Newbury St (Roof) Boston MA
side

Jan 14 2025
Site Inspection Date




INITIAL EVALUATION
PASS/FAIL REPORT
TYPICAL HISTORICAL
EXISTING CONDITIONS



1 S3-BALC-WITH-POST-TO-GROUND
SCALE: 3/8" = 1'-0"

2 S3-3D-RENDERING-BALCONY POST TO GROUND
SCALE: 12" = 1'-0"



3 S4-BALC-WITH-THRU BOLT & PLATE
SCALE: 3/8" = 1'-0"

4 S4-3D-EVAL-RENERING-BALC-WITH THRU BOLT
SCALE: 12" = 1'-0"

COPYRIGHT 2023 ALL RIGHTS RESERVED

12/17/2023 11:57:28 AM

STRUCTURAL SUPPORT COMPONENTS

S3&4

FIRE ESCAPE ENGINEERS | 616 Washington Street, 5th Fl Lynn, MA 01901 | www.fireescapeengineers.com | 800-649-3333

PRE-LOAD TEST INITIAL EVALUATION PASS/FAIL REPORT


E 39-45 Newbury St (Roof) Boston MA
side

Jan 14 2025
Site Inspection Date

PLATFORM and STAIRS COMPONENTS



**INITIAL EVALUATION
PASS/FAIL REPORT**
TYPICAL HISTORICAL
EXISTING CONDITIONS



1 E1-STAIR TYPICAL
SCALE: 1/4" = 1'-0"



2 E1-TOP
SCALE: 3/4" = 1'-0"



3 E1- BOTTOM
SCALE: 3/4" = 1'-0"




4 E1- 3D-EVAL-RENDERING-STAIR TYPICAL
SCALE: 1/2" = 1'-0"




5 T1- TREAD
SCALE: 1" = 1'-0"

CHECKER PLATE TREAD MAKE
24"X24" GRATING COMPONENT.
GISD WILL TELL WHETHER ITS A
CONCRETE GRATE OF
CHECKER PLATE




7 T2 CHECKER PLATE TREAD - PLAN
SCALE: 1" = 1'-0"



BAR GRATE WITH
SPACES AND A THRU
BOLT

6 T1 HISTORIC TREAD - PLAN
SCALE: 1" = 1'-0"



10 G1-3D-EVAL-TREAD
SCALE: 1/2" = 1'-0"

COPYRIGHT 2023 ALL RIGHTS RESERVED

12/17/2023 11:57:26 AM

TREAD & GRATING COMPONENTS

E1,G1&T1

PRE-LOAD TEST INITIAL EVALUATION PASS/FAIL REPORT




E 39-45 Newbury St (Roof) Boston MA
side

Jan 14 2025
Site Inspection Date

CEMENT SLAB, FOOTING & PAD COMPONENTS




INITIAL EVALUATION
PASS/FAIL REPORT
TYPICAL HISTORICAL
EXISTING CONDITIONS



1 C2-CEMENT SLAB, FOOTING AND PAD
SCALE: 3/8" = 1'-0"

2 C2-3D-EVAL-CONCRETE FOOTING
SCALE: 12" = 1'-0"



3 L1-BALCONY AND LADDER
SCALE: 3/8" = 1'-0"

4 L1-3D-EVAL-BALCONY & LADDER
SCALE: 12" = 1'-0"

COPYRIGHT 2023 ALL RIGHTS RESERVED

12/17/2023 11:57:23 AM

CEMENT SLAB, FOOTING & PAD

C2 L1

FIRE ESCAPE ENGINEERS | 616 Washington Street, St #3 Lynn, MA 01901 | www.fireescapeengineers.com | 800-649-3333

PRE-LOAD TEST INITIAL EVALUATION PASS/FAIL REPORT


E side 39-45 Newbury St (Roof) Boston MA

Jan 14 2025
Site Inspection Date

CANTILEVER STAIRS



**INITIAL EVALUATION
PASS/FAIL REPORT**
TYPICAL HISTORICAL
EXISTING CONDITIONS



1 C1-STAIR CANTILEVER

SCALE: 1/4" = 1'-0"

6 C1-ENLGD. 3D BEARING ROD

SCALE:



LOWER CANTILEVER
STAIR RELEASE ROD
AND PUSH BAR

2 C1-TOP

SCALE: 1/2" = 1'-0"




3 C1-BEARING ROD

SCALE: 1/2" = 1'-0"



4 C1-BRACKET BOTTOM

SCALE: 1/2" = 1'-0"



7 C1-3D-EVAL-RENDERING-STAIR CANTILEVER

SCALE: 1/2" = 1'-0"

COPYRIGHT 2023 ALL RIGHTS RESERVED

12/17/2023 11:57:22 AM

CANTILEVER STAIRS

C1

FIRE ESCAPE ENGINEERS | 616 Washington Street, St #3 Lynn, MA 01901 | www.fireescapeengineers.com | 800-649-3333

PRE-LOAD TEST INITIAL EVALUATION PASS/FAIL REPORT


E 39-45 Newbury St (Roof) Boston MA
side

Jan 14 2025
Site Inspection Date

CATWALK COMPONENTS




INITIAL EVALUATION
PASS/FAIL REPORT
TYPICAL HISTORICAL
EXISTING CONDITIONS



1 C3-CATWALK AND COMPONENTS
SCALE: 3/8" = 1'-0"



2 C3-3D-EVAL-RENDERING-CATWALK
SCALE: 1/2" = 1'-0"



4 E2-RAIL WITH EMBED
SCALE: 3/8" = 1'-0"



6 E2-3D-RENDERING-RAILING
SCALE: 1/2" = 1'-0"

COPYRIGHT 2023 ALL RIGHTS RESERVED

13

12/17/2023 11:57:24 AM	CATWALK COMPONENTS	C3&E2
FIRE ESCAPE ENGINEERS 616 Washington Street, St #3 Lynn, MA 01901 www.fireescapeengineers.com 800-649-3333		

NOT to be used as a Construction Control Document unless noted and Formal Repair Report attached.

This document expires 30 days from date of delivery to owner/agent via email or mail unless Design Professional or Other are retained for Engineer Oversight in writing.

PRE-LOAD TEST INITIAL EVALUATION PASS/FAIL REPORT



E
side

39-45 Newbury St (Roof) Boston MA

Jan 14 2025
Site Inspection Date

39-45 Newbury St (Roof)

Site Address

Sal Monteneri

Owner or Owner Agent

Boston

City

MA

State

02116

Zip Code

(617) 728-2759

Phone

fax

smonteneri@dlsaunders.com

email

FE Structural Format

Catwalk

DL Saunders

Owner or Owner Agent Company

Location

E

Mailing Address

FE Made Of
Steel & Wood

Boston

City

MA

State

Zip Code

Stories

6

Phone

fax

of FEs on building

2

website

Boston MA

Authority Having Jurisdiction

1010 Massachusetts Ave

Address

Boston

City

MA

State

02118

Zip Code

neil.sullivan@boston.gov

email

617-961-3434

Phone

fax

Violation Number

WRITTEN VIOLATION VERBAL N

Repair/Paint Vendor or Owner/Agent acceptable by AHJ to repair/paint fire escapes:

Repair Vendor or Agent: Company Name

Repair Vendor or Agent: Contact Name

License Number

Repair Permit Number

This document is
OR

- a. a Pass/Fail Report (not to be used as a construction control document)
- b. a Fail Report with attached repairs report (with photos/drawings and repairs criteria as required for permit if permit is needed)

To the best of my Information, Knowledge, Belief and Opinion that the following statements are true and apply regarding this Fire Escape System as of the date of evaluation above.

Indicate inspection was done by:

- a. a visual walk through of the Fire Escape System all accessible areas only. NO Load Test or destructive testing was performed. Safety hammer testing, scraping, poking, and chipping are all part of visual observation and resulting damage is owner's responsibility to repair or maintain.
- b. an Evaluation of the Fire Escape System from the ground, with or without the use of visual aid, due to NO ACCESS or UNSAFE STRUCTURE WITH LIFE SAFETY ISSUES.

Fire Escape Passed? FAILED MAJOR

Life Safety AHJ approval required

- The System is Certified by Load Test done by Engineering/Testing Agency at 100 lbs per sq foot.
- The System is Certified by Other Evidence of Strength (by full restoration or NEW) in lieu of load test.
- The System is Certified by Opinion Affidavit, accepted by AHJ as ready for use with opinion disclaimer of liability.
- Inspection/Evaluation determined the System FAILED. It is NOT structurally sound and/or painted.

ALL FIRE ESCAPES MUST BE STRUCTURALLY SOUND AND KEPT PAINTED AS PER CODE. Structural connections must be free of all internal rust and sealed from water intrusion. Spot paint every 3-5 years, full paint every 7-10 years and maintain sealant on all critical structural connections.

IFC 1104.16.5.1 Fire escape stairs must be examined every 5 years by a design professional or others acceptable to the Authority Having Jurisdiction and inspection report must be submitted to the AHJ. IBC 1001.3.3 All fire escapes shall be examined and/or tested and certified every five years by a design professional or others acceptable who will then submit an affidavit city official. NFPA LIFE SAFETY CODE 101 7.2.8.6.2 The Authority Having Jurisdiction (AHJ) shall approve any fire escape by Load Test or Certification (other evidence of strength).

Francisco Meneses

Design Professional or Other Name

CS-94862

License Number

Jan/07/26

License Expires Date

866-649-0333

Phone

888-895-7507

fax

Jan/29/25

Site Inspection Date

info@fireescapeengineers.com

email

5901

Case ID

Fire Escape Engineers

Design Company or Other Company Name

616 Washington St

Address

Lynn

City

MA

State

01901

Zip Code

X

1/29/2025

peer reviewed by Fire Escape Engineer Francisco Meneses

PRE-LOAD TEST INITIAL EVALUATION PASS/FAIL REPORT**E 39-45 Newbury St (Roof) Boston MA**
sideJan 14 2025
Site Inspection Date**Responsible Party Assignment as per Code****Fire Escape Inspectors Oversight Options:**

Further information for each option you may have interest in will be sent with a formal proposal upon request. Please reach out after reviewing these options with any questions or concerns. A signature is required with a 35% deposit to initiate any option.

Project Management Oversight (PMO): Oversee our network Vendor, or a Vendor of your choice, to do the work necessary to bring your fire escape into compliance and is certified by a final examination (a Load Test may still be required). Technical Repair report written for project. 3 to 5 Visits with a design professional. Zoom meeting to review all repairs and methodology with the chosen vendor is included. Pictures or video supplied by the vendor on a daily basis. unlimited phone calls or Facetime. Includes final certification. Can be a standalone service if you choose your own vendor.

Vendor Management Oversight: Oversee our Network Vendor, or a Vendor of your choice (who is a fully experienced fire escape technician), to do the work necessary to bring your fire escape into compliance and is certified by a final examination (a Load Test may still be required). Zoom meeting to review all repairs and methodology with the chosen vendor is included. Pictures or video supplied by the vendor on a daily basis. Unlimited phone calls or Facetime. Includes final certification. Can be a standalone service if you choose your own vendor.

Load Test: A stand-alone Load Test can be performed with a Deficiency Report (identifying outstanding distressed conditions not repaired or repaired poorly) if you choose your own vendor for the repair process. A Load Test is performed at 100 lb. per square foot and 200 lb. Lateral force on all railings. Weight used depends on square footage calculated A 5-year certification will be issued for one inspection cycle only.

Fire Escape Services: Restoration - Repairs - Repainting 4 Option Pricing

Full Restoration and Full Paint: Restoration will begin shortly after Emergency Repairs are completed if needed. All major structural connections will be cleaned, primed, sealed, and re-bolted. Any components with more than 25% material in any area will be reinforced or replaced. All Minor connections with internal rust will also be treated in the same manner. All Surface Rust is scraped, primed, sealed with a 50-year paintable silicone, and a full topcoat is applied following EPA Lead guidelines (DTM or Oil Base). After final examination by our Inspector (approved by AHJ) a certification with a 15-25-year structural warranty will be issued. This service will negate any future Load test requirement for up to 25 years with AHJ approval. Includes PMO

Spot Restoration and Full Paint All major connections with excessive internal rust will be cleaned, primed, sealed, and re-bolted. Any minor connections with excessive internal rust will be treated the same. Any components with more than 25% material in any area will be reinforced or replaced. There will be an Integrated Load Test and Dynamic Stress Test to components that were not restored. All Surface Rust is scraped, primed, sealed with a 50-year paintable silicone, and a full topcoat is applied following EPA Lead guidelines (DTM or Oil Base). After final examination by our Inspector (approved by AHJ) a certification with a 10-year structural warranty will be issued on only work performed. The cost of the Spot Restoration can be credited towards a Full Restoration within 5 years (price adjusted for inflation and labor rates at that time), some restrictions may apply. Includes Integrated Load Test and Dynamic Stress Test to components. Includes PMO.

Spot Repair and Spot Paint: Only distressed, extremely poor welding, and/or broken connections will be repaired as needed. Critical deteriorated material will be reinforced or replaced as needed. The entire system will be certified (for 5-years only) by a Full Load Test and Dynamic Stress Test. A Spot Paint includes scraping and priming: loose or peeling paint, surface rust, and repaired areas. A spot topcoat is applied following EPA Lead guidelines. No warranty is offered. Includes Load Test and Dynamic Stress Test to components. Includes VO.



PRE-LOAD TEST INITIAL EVALUATION PASS/FAIL REPORT

E 39-45 Newbury St (Roof) Boston MA
side

Jan 14 2025
Site Inspection Date

